DEVELOPMENT OF AN ALL POSITION AUTOMATIC WELDING MACHINE

December, 1976

maintaining the data needed, and co including suggestions for reducing	lection of information is estimated to ompleting and reviewing the collect this burden, to Washington Headqu ald be aware that notwithstanding an OMB control number.	ion of information. Send comments arters Services, Directorate for Info	s regarding this burden estimate ormation Operations and Reports	or any other aspect of the property of the contract of the con	nis collection of information, Highway, Suite 1204, Arlington
1. REPORT DATE DEC 1976		2. REPORT TYPE N/A		3. DATES COVE	ERED
4. TITLE AND SUBTITLE				5a. CONTRACT	NUMBER
Development of An	All Position Auton	natic Welding Macl	nine	5b. GRANT NUM	MBER
				5c. PROGRAM E	ELEMENT NUMBER
6. AUTHOR(S)				5d. PROJECT NU	JMBER
				5e. TASK NUME	BER
				5f. WORK UNIT	NUMBER
	ZATION NAME(S) AND AE fare Center CD Con 128-9500 MacArth	de 2230 - Design In		8. PERFORMING REPORT NUMB	G ORGANIZATION ER
9. SPONSORING/MONITO	RING AGENCY NAME(S) A	AND ADDRESS(ES)		10. SPONSOR/M	ONITOR'S ACRONYM(S)
				11. SPONSOR/M NUMBER(S)	ONITOR'S REPORT
12. DISTRIBUTION/AVAIL Approved for public	ABILITY STATEMENT ic release, distributi	on unlimited			
13. SUPPLEMENTARY NO	TES				
14. ABSTRACT					
15. SUBJECT TERMS					
16. SECURITY CLASSIFIC	ATION OF:		17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	SAR	87	RESPONSIBLE FERSON

Report Documentation Page

Form Approved OMB No. 0704-0188

TABLE OF CONTENTS

Foreword	•		٠		•	•		•	•	•	•	•	•	•		1
Executive Summary	•															2
Development																
Background .																
Approach															•	4
Specification																
Performance .																
Conclusion .	٠					•							•	•	•	11
Figures															•	12
Electrical Schema	ti	LCS	3												•	17
Welder Schematic	3														•	26

FOREWORD

The purpose of this report is to present the results of one of the research and development programs which was initiated by the members of the Ship Production Committee of The Society of Naval Architects and Marine Engineers and financed largely by government funds through the cost sharing contract between the U.S. Maritime Administration and Bethlehem Steel Corporation. The effort of this project was directed to the development of improved methods and hardware applicable to shipyard welding in the U.S. shipyards.

Mr. W. C. Brayton, Bethlehem Steel Corporation, was the Program Manager. Mr. Malcolm T.Gilliland designed and directed the development work at the Gilliland plant at Peach Tree City, Georgia.

Special acknowledgement is made to the members of Welding Panel SP-7 of the SNAME Ship Production Committee who served as technical advisors in the preparation of inquiries and evaluation of sub-contract proposals.

EXECUTIVE SUMMARY

BACKGROUND

Several vertical butt welding processes are presently available for shipyard use. The equipment currently marketed however has some short-comings. The production and maintenance experience of most yards using this equipment has been disappointing, and the vendors in many cases have not been effectively responsive to the problems.

OBJECTIVE

Develop a welding machine capable of making continuous fully automatic welds on transverse butt joints economically any place on the shell of a ship.

ACHIEVEMENT

The objective was accomplished with respect to hardware in that a machine capable of propelling and controlling the welding heads was built and tested. In order to fully utilize all of the potential hardware, however, it would be necessary to develop processes and procedures which would produce acceptable welds in such high stress areas as the bilge.

ACHIEVEMENT (continued)

Rather than delay development of the total project it was decided to direct present effort to the development of a practical vertical electroslag welder capable of welding vertical shell butts aboard ship and defer new process development and combine it with the effort of one side welding.

A prototype vertical butt welding machine was put into production at Avondale in December 1974 and a few months later a second prototype was put into production at Sparrows Point. Presently at least twelve of these units are in production in several U.S. shipyards and several more are on order and under consideration by other yards.

DEVELOPMENT OF AN ALL POSITION AUTOMATIC WELDING MACHINE

BACKGROUND

Several vertical welding processes have been used with limited success for welding vertical shell butts. Both electrogas and electroslag processes have been used. The inherent disadvantage of the electrogas system for ship-yard use is wind problem with shielding gas. The electroslag process effectively eliminates this problem and recent developments in cored electrodes have improved the deposition efficiency.

Existing equipment was not capable of consistently acceptable performance. Problems with wire feeding and carriage travel and tracking made the equipment cliff icult to operate and costly to maintain. Equipment vendors generally have not been effectively responsive to the problems of the shipyards.

APPROACH

The thoughts and comments from the people who had actual production experience were collected from the Welding Panel SP-7 of the ship production committee of S .N .A .M .E. and used to formulate a performance specification for a machine capable of making continuous fully automatic welds on transverse butt joints economically any place on the shell of the ship.

SPECIFICATION:

- The process and apparatus employed shall be capable of welding transverse butts in the shell of a ship in a single pass with automatic tracking.
- 2. The system should be capable of starting to weld at the point of tangency with the bottom to the upper edge of the shear strake.
- If it is determined that process limitations prevent complete effective accomplishment of the foregoing requirement, the practical effective limits of travel shall be specified in the proposal.
- 4. It is assumed that a machine which would have restrictive limitations would be less complex, less costly and significantly more efficient within its operating limits.
 Alternate proposals could be considered for evaluation.
- 5. The minimum radius of curvature around the bilge might be 6 feet.
- 6. The range of plate thickness could be from $\frac{1}{2}$ "to $\frac{1}{2}$ and during the cours of a continuous weld the thickness from plate to plate might vary by increments of $\pm 3/8$ ".

SPECIFICATION: (cont'd.)

- 7. The gap or opening tolerance for fit-up shall be up to 1/8" more than the minimum requirement for connection between inner and outer shoes.
- 8. The system shall be capable of producing welds which exhibit acceptable quality and internal appearance and meet all physical requirements for A. B. S. grades of carbon steel plates for shipbuilding.

Vendors who in the past had not been very responsive to the problems posed by individual shipyards were not any more responsive to this specification. The proposal of Malcolm T. Gi1liland, Inc. was considered by Panel SP-7 to be the most innovative and completely responsive to the specification.

The total concept of the proposal included a machine capable of starting on the bottom shell and progressing through the bilge and up the side shell.

This involved a transition from multiple submerged arc to electroslag welding by means of retractable sliding copper shoes and electrode wide tubes.

PERFORMANCE

The original prototype unit was developed around a carriage employing four wheel drive and controlled by a magnetic amplifier which maintains constant travel speed regardless of fluctuating torque and load requirements.

PERFORMANCE (cont'd.)

A mock-up made of two 1-1/2" thick plates rolled to a 6 ft. bilge radius with longitudinal framing cut outs 10" x 4" to simulate ship conditions was made for testing. Figures 1, 2, and 3 show the carriage in cliff different positions along the mock-up jig.

The equipment was designed so that it would be as light as possible and so that it could be attached to the plate as easily and quickly as possible.

The equipment attached to the plate consists of a four wheel positive drive system which is fastened to the plate with one spring loaded bolt mechanism. There are two inside and two outside groove guides.

The four wheel drive unit consists of one primary drive motor and gear box which drives two chain operated gear boxes from one main drive shaft. The gear boxes are machined from 6061-T6 aluminum so that the unit can be kept as light as possible. The four drive wheels are case hardened knurled wheels for positive grip to the plate surface. A spring loaded outside shoe arm is attached to the main drive shaft between the gear boxes. This outside water cooled shoe assembly is pinned to and pivots from the other end of the arm mechanism so that it may ride firmly against the plate.

PERFORMANCE (cont' d.)

The spring loaded bolt mechanism which fastens the unit to the plate is mounted to a yoke assembly which pivots from two pins off the top half of the unit. The yoke is designed to travel in the joint design which has a 50° included angle. The unit is mounted to the plate with this bolt, and the nut is simply tightened to the point that the spring applies enough pressure to keep the drive wheel from slipping as the unit moves. Attached to the forward most part of both the upper half and lower half of the equipment are the inside and outside groove guides. The groove guides simply serve the purpose of providing the tracking system so that the equipment travels in position as the weld is made.

In the first proto -type model, the upper half of the equipment contained two aix cylinders which operated a water cooled shoe assembly. This copper backing shoe was positioned as the equipment made its way around the bilge radius and up into the vertical position.

The eqipment was designed for six welding wires fed into the weldment in the flat position. The six wires were fed through three wire guide assemblies, each of which fed two wires. At the point in the course of making a weld where the unit began to start around the bilge radius, it is necessary to extinguish the arcs at two of the three wire feed guides. By doing this, only one wire guide would be used to complete the weld the rest of the way around the bilge and up the vertical

PERFORMANCE (cont¹d.)

side shell to the shear strake. The wire guide assemblies are fastened to insulated guide plates and extended up through the weld joint.

Hardware which would perform the task set forth in the specification was developed and proven operable in the test jig; however, to date there are no acceptable welding processes for welding the flat transverse shell butts, or the bilge shell butts in high strength steel.

In accordance with items 3 and 4 of the specification it was decided that because of process limitations on part of the operation the program would be divided into three separate projects, namely:

- A practical and efficient automatic electroslag machine that would weld vertical shell and bulkhead butts aboard ship.
- 2. In conjunction with project SP-7-703 " Field Applications of of One side Welding", process development would continue simultaneously with the development of a practical and efficient automatic multiple submerged arc machine for welding bottom shell butts aboard ship.

PERFORMANCE. (cont'd)

3. After successful completion of the first two projects effort. would be applied to the development of a process which would be acceptable for the welding of bilge shell butts.

This concept differed from the original in that there might be three different specialized machines for the three different jobs rather than a single versatile machine to do all three. With this thought it was decided to direct the entire effort to completing the first project - a vertical machine.

Work continued at an accelerated pace until the first prototype vertical machine was demonstrated at Avondale in December 1974 and the second one .a few months later at Sparrows Point. Figure 4 shows the second prototype machine. in actual production on a 265,000 DWT tanker at the Sparrows Point yard of Bethlehem Steel Corporation.

After witnessing the demonstrations in actual production. orders for over 12 machines were placed by several other U.S. shippards and they are presently in production and additional orders have been received.

Work has resumed on the process development on project No. 2 and that will be the subject of another report upon. the completion of the project.

CONCLUSION

The first phase of the project - Development of a vertical automatic electroslag butt welding machine has been successfully completed and the equipment is being marketed in the U.S. shipbuilding industry at a competitive price.

Full effort is presently being directed to process development of the second project and the integration of process with hardware to develop a bottom shell butt automatic welding machine .

For those who are interested in further details the following pages are devoted to detailed descriptions and illustrations of the equipment.

ACKNOWLEDGEMENT

The untiring effort of Mr. W. C. Alexander and Mr. D. Phillips and their staff at Avondale along with the similar effort of Mr. J. M. Craun and Mr. O. Tibbetts at Bethlehem helped immeasurably in the final development stage.

FIGURES

(Pages 13-16)




Fig. 1. Power Train on Horizontal Plane of Bilge Radius Mock-Up.




Fig. 2. Power Train Moving Around Bilge Radius Mock-Up.




Fig. 3. Power Train Moving into Vertical Section of Bilge Radius Mock-Up.







Fig. 4. Vertical Butt Welder in Operation on Side Shell.


ELECTRICAL SCHEMATICS

(Pages 18-25)












M-9000 -0060




CONTACTOR CONTROL SCHEMATIC

MOTORIZED VOLTAGE CONTROL








WELDER SCHEMATICS

AND PARTS LISTS


(Pages 27-85)



MTG-9000-0001 MAIN DRIVE UNIT, CLUTCH ASSEMBLY & GEARED DRIVE UNITS PARTS LIST

SEE DRAWING NO. 9000-0001 Page 1 All Information Above This Line Must Accompany Parts Orders

Part No.	Description	Qty . Reqd.
9000-0001-1 9000-0001-IA 9000-0001-IB 9000-0001-2 9000-0001-3 9000-0001-5 9000-0001-6 9000-0001-7 9000-0001-8 9000-0001-10 9000-0001-11 9000-0001-12 9000-0001-13 9000-0001-15 9000-0001-15 9000-0001-16 9000-0001-17 9000-0001-18 9000-0001-19 9000-0001-20	Main drive motor Brush cap Brush 4 pin male plug Auxiliary gear housing Motor adapter plate Auxiliary gear housing cover 1/16 x 3/8 shaft pin 6 tooth pinion Screw (6-32 x 3/8 FCSK) Needle bearing Screw (8-32 x 1-3/4 FCSK) 10 tooth pinion 1/16 x 3/8 shaft pin Outboard retainer ring Inboard retainer ring Roller bearing Auxiliary drive shaft 1/8 x 1/2 woodruff key Cap screw (1/4-20 x 3/4 FCSKSH) 40 tooth gear Gear spacer 56 tooth gear	1 2 1 1 1 1 1 4 1 4 1 4 5 2 1 2 1 2 1
9000-0001-22	Auxiliary driven pinion shaft	1




MTG-9000-0001 MAIN DRIVE UNIT, CLUTCH ASSEMBLY & GEARED DRIVE UNITS PARTS LIST

SEE DRAWING NO. 9000-0001 Page 2

All Information Above This Line Must Accompany Parts Orders

Part No.	Description	Qty. Reqd.
9000-0001-29 9000-0001-30 9000-0001-31 9000-0001-32 9000-0001-34 9000-0001-35 9000-0001-36 9000-0001-37 9000-0001-38 9000-0001-40 9000-0001-41 9000-0001-41 9000-0001-42 9000-0001-43 9000-0001-45 9000-0001-45 9000-0001-47 9000-0001-48 9000-0001-50 9000-0001-50 9000-0001-51 9000-0001-52	Retainer ring Retainer ring Top clutch housing Bottom clutch housing Main drive pinion Bearing housing and adapter 3/32 x 1/2 shaft key Screw (6-32 x 5/8 FCSK) Clutch driving gear Cap screw (10-32 x 1 SH). Bearing cover cap Cap screw (8-32 x 1/4 SH) Retainer ring Bearing Cap screw (10-24 x 11/4 SH) Cap screw (1/4-20 x 1 SH) Cap screw (1/4-20 x 1/4 SH) Clutch disc Clutch driven hub Cap screw (1/4-20 x 1 FSCKSH) Clutch pressure plate Clutch spring Hex nut (10-32) Roller bearing	1 1 1 1 1 1 1 4 1 6 1 4 1 1 4 1 6 1 4 1 6 1 4 1 6 1




MTG-9000-0001 MAIN DRIVE UNIT, CLUTCH ASSEMBLY & GEARED DRIVE UNITS PARTS LIST

SEE DRAWING NO. 9000-0001 Page 3

All Information Above This Line Must Accompany Parts Orders


Part No.	Description	Qty . Reqd.
9000-0001-53	Right hand support arm & drive	1
9000-0001-54	housing Cap screw (6-32 x ½ FSCKSH)	4
9000-0001-55 9000-0001-56	Tractor drive shaft bearing cap Cap Screw (¼-20 x¼ FSCKSH)	1
9000-0001-57	Screw (6-32 x 3/8 PH)	4
9000-0001-58	¼" pipe plug	1
9000-0001-59 9000-0001-60	Bearing ringsmall bearing Bearing ringlarge bearing Roller bearing	2
9000-0001-61	Roller bearing	3
9000-0001-62	Roller bearing	1
9000-0001-63 9000-0001-64	Standard bearing spacer Small bearing spacer	3 1
9000-0001-65	Main drive bearing spacer	į
9000-0001-66 9000-0001-67	Internal small bearing drive sprock Internal large bearing drive sprock	cet 1
9000-0001-67	Main drive bull gear	1
9000-0001-69	Tractor main drive shaft	1
9000-0001-70 9000-0001-71	1-15/32" shaft key Small bearing spacer	1 1
9000-0001-72	Tractor auxiliary drive shaft	1
9000-0001-73	1" shaft key	1
9000-0001-74 9000-0001-75	Idler shaft Oilite idler spacer	1 1
9000-0001-76	ldler sprocket	1
9000-0001-77	Retainer ring	1
9000-0001-78 9000-0001-79	Drive chain Right hand support arm cover	1
9000-0001-80	Tractor drive wheel	4
9000-0001-81	Cap screw (6-32 x ½ FCSKSH)	4
9000-0001-82 9000-0001-83	Cap screw (¼-20 x½ SH) Drive wheel cap	2 1
9000-0001-84	Drive roll spacer	<u>i</u>
9000-0001-85 9000-0001-86	Cap screw (10-24 x ½ SH) Motor drive adapter plate	7
9000-0001-87	Idler support bracket	1
9000-0001-88	Flat washer ¼	3 3
9000-0001-89 9000-0001-90	Cap screw (¼-20 x 3/4 BH) Cap screw (10-24 x 1 BH)	3
9000-0001-91	Tractor drive shaft bearing cap	1
9000-0001-92 9000-0001-93	Cap screw (¼-20 x ½ FCSKSH)	1
9000-0001-93	Cap screw (¼-20 x 1 FCSKSH) Cap screw (10-24 x 1 SH)	4



MTG-9000-0001 MAIN DRIVE UNIT, CLUTCH ASSEMBLY & GEARED DRIVE UNITS PARTS LIST

SEE DRAWING NO. 9000-0001 Page 4


Part No.	Description	Qty. Reqd.
9000-0001-100	Left hand support arm drive housing	1
9000-0001-101 9000-0001-102	Cap screw (6-32 x ½ FSCKSH) Tractor drive shaft bearing cap	4
9000-0001-102	Tractor drive shaft bearing cap Cap screw (1/4-20 x 1/2 FSCKSH)	1
9000-0001-104	Screw (6-32 x 3/8 PH)	4
9000-0001-105	Bearing ringsmall bearing Roller bearing	4
9000-0001-106	Roller bearing	4
9000-0001-107	Standard bearing spacer	4
9000-0001-108 9000-0001-109	Small bearing spacer Internal spacer	4 2 2 2 2 2
9000-0001-110	Internal small bearing drive sprocket	2
9000-0001-111	Internal small bearing drive sprocket Tractor auxiliary drive shaft	$\overline{2}$
9000-0001-112	1" shaft key	
9000-0001-113	ldler shaft	1
9000-0001-114 9000-0001-115	Oilite idler spacer Retainer ring	4
9000-0001-115	Idler sprocket	1
9000-0001-117	Drive chain	1
9000-0001-118	<u>L</u> eft hand support arm cover	1
9000-0001-119	Tractor drive wheel	1
0000 0004 400	(Same as 9000-0001-80Page 3)	1
9000-0001-120 9000-0001-121	Cap Screw (6-32 x 1/2 FCSKSH) Cap screw (1/4-20 x 1/2 SH)	4
9000-0001-121	Drive wheel cap	1
9000-0001-123	Drive roll spacer	1
903G-0001-124	Cap screw (10-24 x ½ SH)	11
9000-0001-125	Idler support bracket	1
9000-0001-126	Cap screw (1/4-20 x 3/4 BH)	3
9000-0001-127	Cap screw (10-24 x 1 BH)	1
9000-0001-128 9000-0001-129	Flat washer` ¼" Cap screw (¼-20 x ½ FCSKSH)	3
9000-0001-129	Tractor drive shaft bearing cap	1



MTG-9000-0002 INSULATED WATER MANIFOLD MOUNTING UNIT WITH TOP PLATE GUIDE PARTS LIST

SEE DRAWING NO. 9000-0002


Part No.	Description	Qty. Reqd.
9000-0002-4 Reel arm so 9000-0002-5 Front guide 9000-0002-6 Guide arm 9000-0002-7 90° elbow 9000-0002-8 Guide-roller opening) 9000-0002-9 Straight wa 9000-0002-10 Cap screw (½ 9000-0002-12 Insulator wa 9000-0002-13 Tube insula 9000-0002-14 Cap screw (½ 9000-0002-15 Lock washer	nnect water fitting cket arm nsulator water fitting with bushing (specify root ater fitting 4-20 x 1 SH) 1/4" Isher tor 1-20 x 1½ SH) 1/4") 8/8-16 x 1 SH) alv. bushing	1 1 2 1 1 2 1 1 2 2 2 2 4 1 1 1



MTG-9000-0003 DOVETAIL TORCH MOUNTING SLIDES, SUPPORT ARMS, AND SUPPORT ARM MOUNTING PLATES PARTS LIST

SEE DRAWING NO. 9000-0003


Part No.	Description	Qty. Reqd.
9000-0003-1 9000-0003-2 9000-0003-3 9000-0003-4 9000-0003-5 9000-0003-6 9000-0003-7 9000-0003-8 9000-0003-9 9000-0003-10 9000-0003-11	Cross slide handle 1/8" x 1" Shaft pin Cross slide adjusting screw Knurled set collar Set screw (10-24 x ¼) Oilite bushing mount End bracket Cap screw (10-24 x 5/8 BH) Cap screw (6-32 x ¼ SH) Thrust race Roller thrust bearing	1 1 1 1 1 1 4 2 2
9000-0003-13 9000-0003-14 9000-0003-15 9000-0003-16 9000-0003-17 9000-0003-18 9000-0003-19 9000-0003-20 9000-0003-21 9000-0003-22 9000-0003-23 9000-0003-25 9000-0003-26 9000-0003-27	Threaded oilite bushing Set screw (10-24 x ½) Grease fitting Slide Base Gibb Cap screw (¼-20 x 1½ SH) Set screw half dog point (10-32 x 1") Nut 10-32 Cross slide block adapter plate Cross slide mount Cap screw (¼-20 x 3/4 SH) Cap screw (¼-20 x 1 FCSKSH) Cap screw (¼-20 x ½ SH) Left hand guide and feed head insulated support arm Right hand guide and feed head insulated	1 1 1 1 1 1 2 2 1 1 1 2 2 1
9000-0003-29 9000-0003-30 9000-0003-31	support arm Left hand support arm mounting plate Right hand support arm mounting plate Cap screw ($\frac{1}{4}$ -20 x 1" SH)	1 1 10
9000-0003-34 9000-0003-35 9000-0003-36	Head mounting insulated spacer Nut ½-20 ½" star washer	2 8 8




MTG-9000-0004 WIRE DRIVE UNIT & TORCH ASSEMBLY PARTS LIST See Drawing No. 9000-0004 Page 1

All Information Above This Line Must Accompany Parts Orders

Part No.	Description	Qty. Reqd.
9000-0004-1 9000-0004-1A 9000-0004-1B 9000-0004-2 9000-0004-3 9000-0004-5 9000-0004-6 9000-0004-7 9000-0004-7 9000-0004-10 9000-0004-11 9000-0004-15 9000-0004-15 9000-0004-17 9000-0004-18 9000-0004-19 9000-0004-20	Wire drive motor Brush cap Brush Auxiliary gear housing Motor adapter plate Auxiliary gear housing cover 1/16 x 3/8 shaft pin 17 tooth pinion Screw (6-32 x 3/8 FCSK) Needle bearing Screw (8-32 x 1-3/4 FCSK) 10 tooth pinion 1/16 x 3/8 shaft pin Auxiliary drive shaft 1/8 x 1/2 woodruff key Retainer ring Retainer ring Gear spacer 34 tooth gear	1 2 2 1 1 1 1 4 1 4 1 1 1 1 2 2 1
9000-0004-34 9000-0004-35 9000-0004-36	4 pin male plug Bearing Screw (¼ -20 x 3/4 FCSKSH)	1 1 2




Part No.	Description	Qty. Reqd.
9000-0004-25 9000-0004-26 9000-0004-27 9000-0004-28 9000-0004-29 9000-0004-30	Short barrel extension Long barrel extension Nozzle lock nut Long barrel extension insulator Tip guide Cap screw (1/4-20 x 3/4 SH)	1 1 1 1 1 2
9000-0004-32	Vertical electro slag tip	1




MTG-9000-0004 WIRE DRIVE UNIT & TORCH ASSEMBLY PARTS LIST

SEE DRAWING NO. 9000-0004
Page 3

Part No.	Description	Qty. Reqd.
9000-0004-22 9000-0004-23 9000-0004-24 9000-0004-37 9000-0004-38 9000-0004-40 9000-0004-40	Barrel insulating washerbottom Barrel lock collar Barrel insulating sleeve bottom et screw (8-32 x 1/4) Inner barrel-insulator Outer barrel Outer barrel rack Screw (6-32 x 1/4 PHST)	1 1 1 2 1 1 1 2




Part No.	Description	Qty. Reqd.
9000-0004-33	Wire liner with retainer	1
9000-0004-42 9000-0004-43 9000-0004-44 9000-0004-45 9000-0004-46	Inner barrel Wire guide Inlet guide Cap screw (5/16-18 x 1 Hex) Set screw (½-20 x 3/8)	1 1 1 2 1




All Information Above This Line Must Accompany Parts Orders


Part No.	Description	Qty. Reqd.
9000-0004-12 9000-0004-13A 9000-0004-14 9000-0004-47 9000-0004-48 9000-0004-49 9000-0004-50 9000-0004-51 9000-0004-52 9000-0004-53 9000-0004-55 9000-0004-55 9000-0004-56 9000-0004-57 9000-0004-58 9000-0004-60 9000-0004-61 9000-0004-62 9000-0004-63 9000-0004-64 9000-0004-65 9000-0004-65 9000-0004-67 9000-0004-67	3/32" wire drive roll 3/32" wire idler roll Idler roll bearing Idler roll bearing shaft Bottom wire drive gear housing Top wire drive gear housing Needle bearing Screw (8-32 x ½ FCSK) Cap screw (½-20 x 1 SH) Felt washer Bearing cap Screw (8-32 x 3/8 FCSK) Drive roll nut 3/8-24 Special Idler roll swivel bracket Idler roll bracket tension screw Shoulder screw for swivel bracket Idler roll bracket tension screw keeper Swivel bracket shim Idler roll bracket tension spring Nut ½-28 Wire drive bull gear Gear spacer Retainer ring Bearing Drive shaft 1/2 x 3/32 woodruff key	1 1 1 1 1 1 1 4 5 1 1 1 1 1 1 1 1 1 1 1
9000-0004-69	Retainer ring	1



Part No.	Description	Qty . Req d.
9000-0004-70 9000-0004-71 9000-0004-72 9000-0004-73 9000-0004-74	Upper rotation arm Barrel insulator washertop Rotation limit collar Rotation adjustment clamping sleeve Rotation adjustment insulating sleeve	1 2 1 1
9000-0004-76 9000-0004-77 9000-0004-78 9000-0004-79 9000-0004-80 9000-0004-81 9000-0004-82 9000-0004-83	3/32 x 1/2 shaft pin Cap screw (8-32 x 1-1/8" SH) Rotation adjustment screw Rotation adjustment spring 1/16 Thrust washer Lower rotation arm 1/8 Thrust washer Thrust collar	1 2 1 1 1 1
9000-0004-85 9000-0004-86 9000-0004-87	3/32 x 5/8 shaft pin Rotation adjustment knob Set screw (8-32 x ¼)	1 1 2




Part No.	Description	Qty. Reqd.
9000-0004-88 9000-0004-89 9000-0004-90 9000-0004-91 9000-0004-92 9000-0004-93	Torch guide bracket Torch guide bracket knob Set screw (8-32 x ¼) Oilite thrust washer Cap screw (¼-20 x ½ SH) Torch rack gear	1 1 2 1 2



MTG-9000-0005 WIRE STRAIGHTENER UNIT PARTS LIST

SEE DRAWING NO. 9000-0005

Part No.	Description	Qty. Reqd.
9000-0005-1 9000-0005-2 9000-0005-3 9000-0005-4 9000-0005-5 9000-0005-6 9000-0005-7 9000-0005-8 9000-0005-9 9000-0005-10 9000-0005-11 9000-0005-12 9000-0005-13 9000-0005-15 9000-0005-15	Wire straightener adapter Wire straightener body assembly Adjustment screw Adjustment block clamp Cap screw (5/16-18 x 1 Hex) 5/16 flat washer Cap screw (¼-20 x 1 SH) ¼ flat washer Tension roller 5/16 Flat washer Nut ¼-20 ¼ lock washer Adjustment screw shim Nut 5/16-18 Wire Guide	1 1 1 1 2 2 2 1 1 1 1 1 1 1




PCALE!	APPROVED BIT	DRAWN BY
DATE:		REVISED
MTG-9	OND AUTOMATIC VERT	TICAL WELDER.
DRAW R	BOLT GUIDE, BRAW BOL	-7. ξ DRAWING NUMBER 9000-000

MTG-9000-0006 DRAW BOLT GUIDE, DRAW BOLT AND PLATE GUIDE ASSEMBLY PARTS LIST

SEE DRAWING NO. 9000-0006

Part No.	Description	Qty. Reqd.
9000-0006-1 9000-0006-2 9000-0006-3 9000-0006-4 9000-0006-5 9000-0006-6 9000-0006-7 9000-0006-8 9000-0006-9	Draw bolt guide Tie plate assembly Draw bolt Draw bolt nut Draw bolt washer Draw bolt spring Cap screw (1/4-20 x 11/4 SH) Nut 1/4-20 Guide roller with bushing (specify root opening)	1 1 1 2 1 2 2 2
9000-0006-9A	Roller pin	2




1		
i .	APPROVED BY:	DRAWN BY 3, O.
DATE: 2-14-76	- 	REVISED

MTG 9000 AUTOMATIC VERTICAL WELDER PAGE 1

FRONT & REAR SHOE WATER COOLING

9000-0007



MTG-9000-0007 FRONT AND REAR SHOE WATER COOLING SYSTEM AND MOUNTING UNIT PARTS LIST


SEE DRAWING NO. 9000-0007 Pages 1 & 2

Part No.	Description	Qty. Reqd.
9000-0007-1 9000-0007-2 9000-0007-3 9000-0007-4 9000-0007-5 9000-0007-7 9000-0007-8 9000-0007-9 9000-0007-10 9000-0007-11 9000-0007-12 9000-0007-13 9000-0007-15 9000-0007-16 9000-0007-17 9013-0007-18 9000-0007-19 9000-0007-20 9000-0007-21 9000-0007-22 9000-0007-23 9000-0007-24 9000-0007-25	Bottom cross tie member Front shoes tension adjusting bolt Front shoe tension spring Front shoe pivot pin mount Cap screw (½-20 x 3/4 SH) Tension bolt lock nut Retainer ring Front shoe pivot pin Pivot arm Front shoe pivot bracketbottom Front shoe pivot brackettop Front shoe Rear shoe Front shoe 45° elbow water fitting Rear shoe water return tube with fittings Rear shoe water return tube with fittings Front shoe water inlet tube with fittings Front shoe water inlet tube with fittings Front shoe water inlet tube with fittings Cooling tube 3/16 x 5/8 dowel pin Cap screw (10-24 x 5/8 SH) Rear axle shaft Oilite spacer Rear axle shaft tension spring	1 1 1 2 10 1 2 1 1 1 1 1 1 2 2 1 1 1 1 1
9000-0007-27 9000-0007-28 9000-0007-29	Drive roll spacer (long) Drive roll spacer (short) Tractor drive wheel (same as 9000-0001-80 Page 3)	2 2 2
9000-0007-30 9000-00007-31 9000-0007-32 9000-0007-33 9000-0007-34 9000-0007-35 9000-0007-36	Rear carrier Shoulder bolt (½ x ½) Rear carrier bearing wheel Tie plate pin 1/16 spacer Rear shoe guide arm Guide roller with bushing (specify root opening)	1 4 4 1 4 1
9000-0007-36A 9000-0007-37 5000-0007-38 9000-0007-39	Roller pin Cap screw (10-24 x ½ SH) Right hand rear shoe support arm Left hand rear shoe support arm	1 1 1

MTG-9000-0007 FRONT AND REAR SHOE WATER COOLING SYSTEM AND MOUNTING UNIT PARTS LIST

SEE DRAWING NO. 9000-0007 Pages 1 & 2


Part No.	Description	Qty. Reqd.
9000-0007-40 5000-0007-41 9000-0007-42 9000-0007-43 9000-0007-44	Support arm spacer Support arm tie bar Cap screw (8-32 x 3/4 SH) Rear shoe to support arm bracket Rear shoe tension spring	2 1 2 2 2
9000-0007-45 9000-0007-46	Cap screw (¼-20 x ½ FCSKSH) Cap screw (¼-20 x 1 FCSKSH)	6 4



MTG-9000-0008 FLUX DISPENSER, FLUX HOPPER, AND FLUX GUIDE PARTS LIST


SEE DRAWING NO. 9000-0008

Part No.	Description	Qty . Reqd.
9000-0008-1 9000-0008-2 9000-0008-3 9000-0008-4 9000-0008-5 9000-0008-7 9000-0008-7 9000-0008-1 9000-0008-11 9000-0008-12 9000-0008-13 9000-0008-15 9000-0008-15 9000-0008-16	Flux dispenser body Flux dispenser cap Flux dispenser mounting bracket Dispenser Funnel Cap washer Rotor washer Oilite bushing Rotor blade Flux dispenser rotor Flux feed tube Flux tube insulated end 1/2 " tube clamp Feed tube retainer nut & ferrule Tube to funnel adapter Knob	1 1 2 1 1 2 2 2 2 2 6 1 1 1 1 1
9000-0008-18 9000-0008-19 9000-0008-20	Set screw (8-32 X½) Cap screw (10-24 X½ SH) Cap screw (10-24 x 5/8 SH)	2 14 2



MTG-9000-0009 WIRE REEL MOUNTING UNIT PARTS LIST SEE DRAWING NO. 9000-0009


Part No.	Description	Qty. Reqd.
9000-0009-1 9000-0009-2 9030-0009-3 9000-0009-4 9000-0009-5 9000-0009-7 9000-0009-7 9000-0009-10 9000-0009-11 9000-0009-12 9000-0009-13 9000-0009-14 9000-0009-15 9000-0009-15 9000-0009-17 9000-0009-18 9000-0009-19	Reel arm Coil holder for welding wire Reel arm coil holder bracket Self locking nut (½-20) Machine screw (½-20 x l½ FH) Bracket insulator washer Coil holder insulator tube Coil holder insulator washer Key lock washer Coil holder tension spring T washer Cap screw (3/8-16 x 1½ Hex) Stud lock nut 1/8 x 1 shaft pin Coil holder wire tension stud Tension stud pivot arm Pivot arm tension spring 3/8" flat washer Tension wing nut	1 1 1 2 2 1 1 1 1 1 4 4 4 4 4 4 4



MTG-9000-0010 REMOTE VOLTAGE CURRENT AND TRAVEL CONTROL UNIT PARTS LIST

DRAWING NO. 9000-0010


Part No.	Description	Qty . Reqd.
9000-0010-1 9000-0010-2 9000-0010-3 9000-0010-5 9000-0010-6 9000-0010-8 9000-0010-9 9000-0010-10 9000-0010-11 9000-0010-12 9000-0010-13 9000-0010-14 9000-0010-15 9000-0010-16 9000-0010-17 9000-0010-18 9000-0010-19 9000-0010-20 9000-0010-21 9000-0010-22	Case Case cover Instrument protection arm 55 pin male socket 6 pin female socket (small) 4 pin female socket Weld-inch switch Forward-off-reverse switch Increase-decrease voltage switch Volt-amp switch for meter Manual-automatic travel switch Forward-off-reverse travel switch Wire speed rheostat Travel speed rheostat Volt-ammeter 4 pin female socket Resistor 8W 100 ohm Screw (4-40 x ½ FCSK) Screw (8-32 x ½ Truss head) 500 ohm ½ watt resistor 330 ohm ½ watt resistor 270,000 ohm ½ watt resistor	1 1 1 1 1 1 1 1 1 1 1 1 2 8 2 1 1 1



MTG-9000-0011 CONTROL CABLE, ELECTRODE CABLE, AND WATER HOSE ASSEMBLY COMPLETE WITH QUICK DISCONNECT FITTINGS PARTS LIST

SEE DRAWING NO. 9000-0011


Part No.	Description	Qty. Reqd.
9000-0011-1 9000-0011-2 9000-0011-3 9000-0011-4 9000-0011-5 9000-0011-6	55 pin female plugtractor end 55 pin male plugpower source end Electrode cabletractor mounted 36" (Specify 2/0 or 4/0) Female quick disconnectelectrode Female quick disconnectwater Male quick disconnectwater	1 1 1 2 4
9000-0011-8	Lug for electrode cable	2
9000-0011-10 9000-0011-11 9000-0011-12 9000-0011-13 9000-0011-14	Cap screw (1/2-13 x 1 Hex) Hex nut 1/2-13 3/8 nut and nipple Hose clamp Multi-conductor control cable (specify length)	1 1 1 8 1
9000-0011-15 9000-0011-16 9000-0011-17 9000-0011-18 9000-0011-19	Electrode cable mounting clamp Male quick disconnectelectrode 3/8 water hose-tractor mounted 241" 3/8 water hose (Specify length) Electrode cable (Specify length and specify 2/0 or 4/0)	1 1 2 2 1



MTG -9000-0012 REMOTE METER RELAY TRAWEL DRIVE PARTS LIST SEE DRAWING NO. 9000-0012

All Information Above This Line Must Accompany Parts Orders


Part No.	Description	Qty. Reqd .
9000-0012-1	Case	1
9000-0012-2	Case cover	1
9000-0012-3	Case handle	1
9000-0012-4	Meter relay	1
9000-0012-5	6 pin male plug (small)	1
9000-0012-6	6 pin male plug (large)	1
9000-0012-7	Multi-conductor cable 10'	1
9000-0012-8	6 pin female socket (large)	$\bar{1}$
9000-0012-9	Screw (6-32 x 1/4 STPH)	4
9000-0012-10	Screw (4-40 x ¼ PH)	8
9000-0012-11	Screw (10-32 x $\frac{1}{4}$ " PH)	8



MTG-9000-0013 MAIN CONTROL BOX PARTS LIST

SEE DRAWING NO. 9000-0013 Page 1


Part No.	Description	Qty . Reqd.
9000-0013-1	Case	1
9000-0013-2	Case cover	1
9000-0013-3 9000-0013-4	Travel and wire feed relay panel assembly Travel and wire feed magnetic amplifier panel assembly	2 2
9000-0013-5	55 pin female socket	1
9000-0013-6	5 pin female socket	1
9000-0013-7	8 pin female socket	1



MTG-9000-0013 TRAVEL AND WIRE FEED RELAY PANEL PARTS LIST

SEE DRAWING NO. 9000-0013 Page 2


Part No.	Description	Qty. Reqd.
9000-0013-8 9000-0013-9 9000-0013-10 9000-0013-11 9000-0013-12 9000-0013-13 9000-0013-15 9000-0013-16 9000-0013-16A 9000-0013-16B 9000-0013-17A 9000-0013-17A 9000-0013-17B 9000-0013-18B 9000-0013-18C 9000-0013-19	Relay-RR-120VAC. Relay-MR-100VAC. 12 pt. terminal block 10 ohm 25w resistor 500 ohm 25W resistor for travel relay panel 200 ohm 25W resistor for wire feed relay panel Screw (10-32 x 2-3/4 RH) Insulating washer Hex nut 10-32 #10 lock washer #10 flat washer Screw (6-32 x ½ PH) Hex nut 6-32 #6 lock washer Screw (8-32 x 5/8 PH) Hex nut 8-32 #8 lock washer #8 flat washer Panel only	1 1 1 1 1 2 4 2 2 2 2 2 2 2 2 4 4 4 4 4



MTG-9000-0013 TRAVEL AND WIRE FEED MAGNETIC AMPLIFIER PANEL ASSEMBLY PARTS LIST


SEE DRAWING NO. 9000-0013 Page 3


Part No.	Description	Qty. Reqd.
9000-0013-20 9000-0013-21 9000-0013-22 9000-0013-23 9000-0013-24 9000-0013-25 9000-0013-26 9000-0013-27	Small transformer Large transformer 400 ohm 25W resistor 1000ohm 25W resistor Feedback switch 8 pin octal socket Arc-input switch 3 fuse mount	1 1 1 1 2 2 2
9000-0013-29 9000-0013-30 9000-0013-31 9000-0013-32 9000-0013-33 9000-0013-34 9000-0013-35 9000-0013-36	30MFD 150WV capacitor Rubber grommet 1½ amp AGC fuse 4 amp MDL fuse ½ amp AGC fuse Standard #58 diode bridge Double diode bridge 16 pt. terminal block	1 5 2 1 3 1 1
9000-0013-38 9000-0013-39 9000-0013-40 9000-0013-41 9000-0013-42 9000-0013-43 9000-0013-44 9000-0013-45 9000-0013-46	Screw (10-32 x 2-3/4" RH) Insulator washer Switch panel only 50-50 MFD 150WV capacitor Magnetic amplifier panel only 4 pt. terminal block Hex nut 10-32 #10 flat washer #10 lock washer Magnetic amplifier coil assembly	2 4 1 1 1 2 2 2 2




MTG-9000-0014 WATER CIRCULATOR SYSTEM PARTS LIST SEE DRAWING NO. 9000-0014

Part No.	Description	Qty. Reqd.
9000-0014-1 9000-0014-2 9000-0014-3 9000-0014-4 9000-0014-5 9000-0014-7 9000-0014-8 9000-0014-9 9000-0014-10 9000-0014-11 9000-0014-13 9000-0014-15 9000-0014-15 9000-0014-16 9000-0014-17 9000-0014-18 9000-0014-19 9000-0014-20	Case Radiator Pump Fan motor Radiator cap Reservoir cap Fan blade 1½ hose12" long 1½ hose22"long 1" pipe17" long Pressure gauge 1½ hose19" long 1¼ hose14" long 1¼ hose6" long Drain plug 3 pin male twist lock plug 1" pipe coupling 1" to ½" pipe bushing ½" pipe thread female quick disconnect fit Pressure regulator	1 2 1 1 2 1 1 1 1 1 1 1 1 1 2 2 2 1 1 1 2 1 1 1 1 2 1 1 1 1 2 1 1 2 1 1 2 1 1 2







MTG-1100 POWER SOURCE

Item No.	Part No.	Description
1 2 3 4 5 6 7 8	MTG-S1100-11001 MTG-S1100-11002 MTG-S1100-11003 MTG-S1100-11004 MTG-S1100-11005 MTG-S1100-11006 MTG-S1100-11007 MTG-S1100-11008 MTG-S1100-11009	Power Source Main Case Cover for Right Side-Power Source Cover for Left Side-Power Source Top Cover for Power Source Lifting eye-Power Supply (2 required) Top Cover Mounting Bolt(2 required) Side Cover Mounting Bolt (20 Required) {MIG-60 Control Box, Complete) (MTG-60-69 Multi Conductor
10 11	MTG-S1100-11010 MTG-S1100-11011	Control Lead) Pilot Light Manual-Automatic Water Control
12 13	MTG-S1100-11012 MTG-S1100-11013	Switch On-off Main Power Switch Raise-Lower Automatic Voltage Adjustment Switch
14 15 16 17 18 19	MTG-S1100-11014 MTG-S1100-11015 MTG-S1100-11016 MTG-S1100-11017 MTG-S1100-11018 MTG-S1100-11019 MTG-S1100-11020	Voltmeter 0-50 V. DC 0-1500 Amp Ammeter DC Clear Plastic Voltage Vernier Cover Top Diode Stack Louver Fan Shroud Louver Fan Shroud Mounting Bolts for Fan Shroud
21 22 23 24 25	MTG-S1100-11021 IWG-S1100-11022 MTG-S1100-11023 MTG-S1100-11024 MTG-S1100-11025	(2 Required) Nameplate 5 Pin Socket 8 Pin Socket Burnback Adjustment Control Sub Arc/Auto Vertical Conversion
26 27 28 29 30	MTG-s1100-11026 MTG-S1100-11027 MTG-S1100-11322 MTG-S1100-11348 MTG-S1100-11869	Switch 15 Amp Fuse Holder Water Control Recepticle Inductor Auto Transformer Variable Transformer
31 32 33 34 35	MTG-S1100-11346 MTG-S1100-11032 MTG-S1100-11033 MTG-S1100-11034 MIG-S1100-11035	Stepdown Transformer Top Plate for Diode Stack Bottom Plate for Diode Stack Diode (3 Required) Diode (3 Required)
36 37 38	MTG-s1100-11036 MTG-S1100-11037 NTG-S1100-11038	Diode Stack Mounting Bolts Diode Stack Mounting Insulator Plate (2 Required) Spacers (4 Required)
39 40 41 42	MTG-S1100-11039 MTG-S1100-11040 MTG-S1100-11041 MTG-S1100-11042	Insulator Mounting Bolts, Nuts and Washers (8 required) Mounting Washers (8 required) Nuts (4 Required) Diode Mounting Washer (6 Required)

MTG-1100 Power Source

Part No.	Description
MTG-S1100-11043	Diode Mounting Lock Washer
MTG-S1100-11044	(6 Required) Diode Mounting Nut
MTC-91100-11045	(6 Required) Bracket-Inductor to Diode Stack
MTG-S1100-11046	Insulator
MTG-S110-11047	Diode Lead Mounting Bracket (3 Required)
MTG-S1100-11048	Fuse (6 Required)
MrG-S1100-11049	Insulator Supports (3 Required)
MTG-S1100-11050	Fuse Mounting Bracket (3 Required)
MTG-S1100-11051	Transformer Shunt Bar (3 Required)
MTG-S1100-11052	Cable-Inductor to Positive Output Shunt
MTG-S1100-11053	Positive Shunt Bar
MTG-S1100-11054	Negative Shunt Bar
MIG-S1100-11055	Negative Shunt Bar Mounting Bracket
MIG-S1100-11056	Bolt, Shunt Bar Mounting
MTG-S1100-11057	Flat Washer-¼ inch thick (8 Required)
MIG-S1100-11058	Flat Washer, Shunt Bar Mounting
	Nut, Shunt Bar Mounting
MTG-S1100-11060	Bolt, Positive shunt Bar Mounting (3 Required)
MTG-s1100-11061	Flat Washer, Positive Shunt Bar Mounting
MTG-S1100-11062	Nut, Positive Shunt Bar Mounting
	Bolt, Output Shunt Bar
	Washer, Output Shunt Bar
	Nut, Output Shunt Bar
	Output Shunt Bar (2 Required)
MIG-S1100-1106/	Bolt,Flat Washer, Lock Washer (2 Required)
MIG-S1100-11068	Output Insulator Mounting Bracket
MTG-S1100-11069	Bolt,Cable to Output Shunt Bar (4 Required)
MTG-S1100-110700	Washer (4 Required)
	Nut (4 Required)
	Insulator (2 Required)
	Relay
	Receptacle
MTG-S1100-11074	Fan Motor
	MTG-S1100-11044 MTG-S1100-11045 MTG-S1100-11047 MTG-S1100-11047 MTG-S1100-11048 MrG-S1100-11049 MTG-S1100-11050 MTG-S1100-11051 MTG-S1100-11052 MTG-S1100-11053 MTG-S1100-11054 MIG-S1100-11055 MIG-S1100-11056 MTG-S1100-11057 MIG-S1100-11058 MTG-S1100-11060 MTG-S1100-11061 MTG-S1100-11061 MTG-S1100-11063 MTG-S1100-11063 MTG-S1100-11065 MTG-S1100-11065 MTG-S1100-11066 MIG-S1100-11067 MIG-S1100-11069 MTG-S1100-11069 MTG-S1100-110700 MTG-S1100-11071 MTG-S1100-11072 MIG-S1100-11073 MTG-S1100-11073 MTG-S1100-11074

MT G-1100 POWER SOURCE

Item No.	Part No.	Description
76	MTG-S1100-11076	Fan Blade
77	MTG-S1100-11077	Fan Blade Set Screw
78	MTG-S1100-11078	Terminal Strip
79	MTG-S1100-11079	Burnback Panel
80	MTG-S1100-11080	Terminal Strip
81	MTG-S1100-11081	l½ Amp Fuse
82	MTG-S1100-11082	Burnback Potentiometer
83	MIG-S1100-11083	Pesistor
84	MIG-S1100-11084	Diode Bridge
85	MTG-S1100-11085	Relay
86	MIG-S1100-11086	Input Voltage Panel
87	MTG-S1100-11087	Bracket
88	MTG S1100-11088	Limit Switch (2 Required)
89	MTG-S1100-11089	Mounting Bracket for Limit Switch
90	MTG-S1100-11090	Voltage Adjustment Motor Mounting Bracket
91	MTG-S1100-11091	Capacitor
92	MTG-S1100-11092	Voltage Adjustment Motor
93	MTG-S1100-11093	Sprocket
94	MTG-S1100-11094	Chain
95	MTG-S1100-11095	Brush Holder Assembly
96	MTG-S1100-11096	Limit Switch Stop Bracket
97	MTG-S1100-11097	Mounting Bracket for Voltage Vernier
98	MTG-S1100-11098	Voltage Vernier
99	MTG-S1100-11099	Botton Brush Holder Mounting Plate
100	MTG-S1100-11100	Top Brush Holder Mounting Plate
101	MTG-S1100-11101	Sprocket (2 Required)
102	MTG-S1100-11102	Cotter Pin
103	MTG-S1100-11103	Support Guide Rods (2 Required)
104	MTG-S1100-11104	Threaded Guide Rod (2 Required)
105	MTG-S1100-11105	Brush Guide Insulator Strip (2 Required)
106	MTG-S1100-11106	Brush Holder Insulator End Bracket (2 Required)
107	MIG-S1100-11107	Brush Holder Insulator Guide
108	MTG-S1100-11108	Bracket-Left Side Brush Holder Insulator Guide
109	MTG-S1100-11109	Bracket-Right Side Brush Holder Threaded Guide Stop <i>(2</i> Required)

MTG-1100 POWER SOURCE

Item No.	Part No.	Description
110	MTG-S1100-111IO	Brush Holder Front Insulator Strip
111	MTG-S1100-11111	Mounting Bolt (3 Required)
112	MTG-S1100-11112	Washer (3 Required)
113	MTG-S1100-11113	Brush Pigtail Mounting Bolt (3 Required)
114	MTG-S1100-11114	Washer (3 Required)
115	MTG-S1100-11115	Nut (3 Required)
116	MTG-S1100-11116	Brush (12 Required)
117	MTG-S1100-11117	Spring (12 Required)
118	MTG-s1100-11118	Mounting screw (2 Required)
119	MTG-S1100-I1119	Fuse Block
120	MTG-S1100-11120	Capacitor
121	MTG-S1100-11121	Support Guide Insulator (2 Required)